ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
1

Ward Name
Kempegowda Ward

Street ID
W0138, W0132, W0174, W0142, W0146, W0154, W0166, W

Street Name
2nd Crs, NA, 3rd Crs

Significant Landmark
MARUTHINAGARA 1ST Main Road from (CH 450 to 892.00

Segment No.
1/C-W0138/S113810

Total Length (m)
542.13

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	167.12	77.607409	13.111209	77.606111	13.111073	W0138	W0517
2	375.01	77.607720	13.111706	77.606294	13.108618	W0166	W0128

Work Details

History of Road / Lane / Circles

Name of the Work
Asphalting and Improvements to Roads at MARUTHINAGARA 1ST Main Road from (CH 450 to 892.00mtr) in Ward no 01 of Yelahanka Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
9500000

Sanctioned Year
2017

Year
2017 - 2018

Type of Work
Asphalting

Other Work Type

Tender
Not a Tender

Work Details
Asphalting and Improvements to Roads at MARUTHINAGARA 1ST Main Road from (CH 450 to 892.00mtr) in Ward no 01 of Yelahanka Sub-Division Yelahanka zone

Job No. / Work Code
001-17-000060

Work Order No.
BBMP/EE (YNK.D)/WO/87/2017-18

Work Order Date
30/06/2017

Period of Extention
90 DAYS

Defect Liability Period From
30/07/2017

Defect Liability Period To
29/07/2018

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
KRIDL

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Field Inspection Details

Number of Trees

12

Any Other Information

Name

SACHIN

Date of Inspection

07/08/2017

Remarks

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0138, W0132, W0174, W0142,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0138, W0132, W0174, W0142,

Road Condition

This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	07/08/2017	06/09/2017	COMPLETED
SE	VASU K M	07/08/2017	06/09/2017	COMPLETED
EE	VASU K M	07/08/2017	06/09/2017	COMPLETED
AEE	DEVARAJ	07/08/2017	06/09/2017	COMPLETED
AE	SACHIN	07/08/2017	06/09/2017	COMPLETED
AE	SACHIN	07/08/2017	06/09/2017	COMPLETED

Zone: YELAHANKA Ward No: 1 Ward Name: Kempegowda Ward Street ID: W0138, W0132, W0174, W0142,